

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SGV 7K Pad**  
**Location ID: 334366**



**Location Overview: Location is approximately 520 yards from  
Pete & Bill creek. Location is within Black Bear Habitat area &  
in close proximity to NSO Habitat area.**

**Section/Township/Range: 7 8S95W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SGV 7K Pad**  
**Location ID: 334366**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SGV 7K Pad**  
**Location ID: 334366**



**Photo # 6909 Rock socks/BMP's laying along side road & not in use in multiple areas**



**Photo # 6911 Rock socks/BMP's laying along side road & not in use in multiple areas**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SGV 7K Pad**  
**Location ID: 334366**



**Photo # 6912 Sediment trap needs maintenance (approximately 20-30 yards after you turn onto spur road to location)**



**Photo # 6914 Sediment trap needs maintenance (approximately 20-30 yards after you turn onto spur road to location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SGV 7K Pad**  
**Location ID: 334366**



**Photo # 6915 Sediment trap needs maintenance  
(approximately 20-30 yards after you turn onto spur  
road to location)**