

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7139 From entrance to location



Photo # 7140 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7146 Location



Photo # 7147 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7148 Location



Photo # 7149 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7150 Location



Photo # 7152 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7153 Debris



Photo # 7154 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7160 Debris



Photo # 7161 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7155 Chemical tank label/information illegible



Photo # 7179 Some info on wellhead sign illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-05 Pad

Location ID: 334423



Photo # 7180 Some info on wellhead sign illegible



Photo # 7181 Some info on wellhead sign illegible