

Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



Photo # 7502 From entrance to location



Photo # 7503 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



Photo # 7506 Location

Photo # 7507 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad
Location #: 334892



Photo # 7508 Location



Photo # 7509 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



Photo # 7510 Location



Photo # 7514 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad
Location #: 334892



Photo # 7515 Location/Nitrogen tank



Photo # 7529 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



Photo # 7530 Debris



Photo # 7533 Open ended load line