

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2023

Submitted Date:

08/30/2023

Document Number:

707601767

FIELD INSPECTION FORM

Loc ID 438449 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438450	WELL	PR	06/01/2023	OW	123-39978	Chesnut 27O-243	SI
438451	WELL	PR	06/01/2023	OW	123-39979	Chesnut 27O-303	SI
438452	WELL	PR	06/01/2023	OW	123-39980	Chesnut 27K-323	SI
438453	WELL	PR	10/01/2022	OW	123-39981	Chesnut 27K-403	PR

General Comment:

This is a WELL inspection.
Well(s): 1: Producing | PR ; 3: Shut-In | SI.
Battery: Active.

Centralized Battery serves 2 Location IDs (438631, 438449).
(Well(s): 3: Producing | PR ; 5: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:
A.) Field Inspection Report doc. #707601765 and/or Location ID #438631 for Well(s) info.
B.) Field Inspection Report doc. #707601769 and/or Location ID #438631 for Battery / Facility, Equipment info.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	4: Wellsites.	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	4: Wellsites. Iron panel.	
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 4		
	Comment:	4: Wellsites. Appears plumbed to surface.	
Corrective Action:			Date:
Type: Plunger Lift	# 4		
	Comment:	4: Wellsites.	
Corrective Action:			Date:

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.370468,-104.542916	
	Comment:	Centralized Battery serves 2 Location IDs (438631, 438449). (Well(s): 3: Producing PR ; 5: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 438450 Type: WELL API Number: 123-39978 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed prod valves shut.
CECMC records last prod: 11/2022.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 438451 Type: WELL API Number: 123-39979 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed prod valves shut.
CECMC records last prod: 12/2022.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 438452 Type: WELL API Number: 123-39980 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed prod valves shut.
CECMC records last prod: 10/2022.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 438453 Type: WELL API Number: 123-39981 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p style="color: blue; margin: 0;">CECMC Inspection Report Summary:</p> <p style="color: blue; margin: 0;">On WED 08/23/2023 at approximately 15:11 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: Chesnut/27K-HZ Pad Location ID: 438449 Well Name(s): Chesnut 270-243, Chesnut 270-303, Chesnut 27K-323, Chesnut 27K-403. API: 123-39978, 123-39979, 123-39980, 123-39981. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p style="color: blue; margin: 0;">While there, I observed: Well(s): 1: Producing PR ; 3: Shut-In SI. Battery: Active.</p> <p style="color: blue; margin: 0;">Centralized Battery serves 2 Location IDs (438631, 438449). (Well(s): 3: Producing PR ; 5: Shut-In SI).</p> <p style="color: blue; margin: 0;">Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p style="color: blue; margin: 0;">Reference: A.) Field Inspection Report doc. #707601765 and/or Location ID #438631 for Well(s) info. B.) Field Inspection Report doc. #707601769 and/or Location ID #438631 for Battery / Facility, Equipment info.</p> <p style="color: blue; margin: 0;">During this inspection, NO possible compliance issues were observed.</p> <p style="color: blue; margin: 0;">This is a summary of the inspection report.</p>	evinsb	08/30/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601768	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237880