

**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**



**Access road to location**



**As entrance signs are replaced additional information will be required**



**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**



**Entrance to location**



**Weeds**



**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**



**Weeds**



**Open end loadline. Valve left open**



KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257



**No weed maintenance**



**Weeds**



**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**




**As wellhead signs are replaced additional information will be required**



**Stained soil under separator**



**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**



**Debris**




**Stained soil**

KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257



Debris



Calibration out of date



KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257



**Debris**



**Weeds covering location**



**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**



**Location from Northwest corner**



**Location from Southwest corner**



**KT Resources LLC  
WRD Unit 28-11  
Loc ID: 316257**



**Location from Southeast corner**



**Location from Northeast corner**