

Cow Skull 11-89-18 Pad —Location ID—414132

Inspection Doc -708300783—8/14/2023

CA #1 of 1— Rill erosion cutting through lease road.

Lease road degradation from ditch digging.





Cow Skull 11-89-18 Pad —Location ID—414132

Inspection Doc -708300783—8/14/2023

CA #1 of 1—1— Road Maintenance Completed 8/24/23





Cow Skull 11-89-18 Pad —Location ID—414132

Inspection Doc -708300783—8/14/2023

CA #1 of 1—1— Road Maintenance Completed 8/24/23





Cow Skull 11-89-18 Pad —Location ID—414132

Inspection Doc -708300783—8/14/2023

CA #2 of 2—2— Unprotected Soil Stockpile—Landowner Rock Pile

Wattles placed 8/30/2023





Cow Skull 11-89-18 Pad —Location ID—414132

Inspection Doc -708300783—8/14/2023

Comment— Readable Label on Antifreeze Tank Missing

