

Inspection Photos

8/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 479149

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



August 21, 2023



August 21, 2023

Photo 1: Location overview. Photos also example showing drill cuttings have been removed from the trench, and stored over areas of the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



Photo 2: Photos show the cuttings trench; drill cuttings have been removed from the trench, and stored over areas of the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479149



Photo 5: Location signage and permit information.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



Photo 5: Signage/Labels missing from the Battery facility and tanks.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources