

# Inspection Photos

8/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 335720

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335720



**Photo 1:** Working Pad overview.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 335720



**Photo 2:** Signage at the tank battery not posted, or not conspicuous.




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335720



**Photo 3:** Example of uncapped lines observed at separators.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 335720



**Photo 4:** Exposed pipe on WPS.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335720



**Photo 5:** Unused equipment.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 335720



**Photo 6:** Photos examples of interim areas where additional work may be required to achieve uniform vegetation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 335720



**Photo 7:** Unmaintained culvert on the west end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources