

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location ID: 324091

Date: 8/22/2023



Wellhead – Photo #06005



Separator – Photo #06006

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location ID: 324091

Date: 8/22/2023



Aug 22, 2023 at 10:11:38  
Parachute CO 81635  
United States



Aug 22, 2023 at 10:20:36  
Parachute CO 81635  
United States

**Tank Battery – Photo #06007**

**Rill Erosion on Access Road – Photo #06011**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location ID: 324091

Date: 8/22/2023



**Rill Erosion on Access Road – Photo #06012**



**Rill Erosion on Access Road – Photo #06013**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location ID: 324091

Date: 8/22/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #06014