

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 8/22/2023



South End of Location – Photo #06029



Wellheads – Photo #06030

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 8/22/2023



Separators – Photo #06034



Tank Battery – Photo #06035



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 8/22/2023



Debris Near Tank Battery – Photo #06036



Insufficient Erosion Control – Photo #06037



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location ID: 311586

Date: 8/22/2023



**Insufficient Erosion Control – Photo #06039**