

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K32 Pad**  
**Location #: 334837**



**Photo # 7766 From entrance to location**



**Photo # 7768 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K32 Pad**  
**Location #: 334837**



**Photo # 7769 Location**



**Photo # 7770 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K32 Pad**  
**Location #: 334837**



Aug 30, 2023 at 12:05:35 PM  
CO



Aug 30, 2023 at 12:10:49 PM  
CO

**Photo # 7772 Location**

**Photo # 7775 Unmarked/improperly marked deadman**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K32 Pad**  
**Location #: 334837**



**Photo # 7776 Same Unmarked/improperly marked deadman from a different angle**