



02158727

WELL SITE INSPECTION

OPERATOR CLYDE NEILL / FRICK CODATE 11/1/84WELL NAME #1 G.F. GRAHAMCOUNTY LAS ANIMASRIG —LEGAL NENE S 7 T28S R52WSURFACE CASING — SIZE 7" DEPTH 360 DATE 8-1-1948CEMENT VOLUME — RETURNS — WOC —PROBABLE FOX HILLS DEPTH —MUD PITS NONEDISPOSAL —PRODUCTION STRING — SIZE 5" DEPTH —STAGED — CBL CHECKED —SQUEEZE — FRAC JOB —BATTERY NONE SIGN NONE

SITE INSPECTION AFTER DRILLING 5" CASING POORLY CAPPED AS TO
NOT EFFECT A SEAL - GAS LEAKING BY CAP. STRONG BLOW OF
GAS (PROBABLY CO₂) COMING OUT OF 7" X 5" CSG. ANNULUS.

DIRECTIONS SOUTH FROM LA JUNTA ON Hwy 109TO LAS ANIMAS COUNTY LINE - HEAD EAST ONROAD AT COUNTY LINE FOR 4 1/2 MI - TO GATEACCESS ROAD TO THE RIGHT.ACTION PLUG WELLENGINEER ROBERT VACLAVIK