



02158729

## WELL SITE INSP

OPERATOR CLYDE NIELL / FRICK COWELL NAME #3 G F GRAHAM

RIG \_\_\_\_\_

SURFACE CASING \_\_\_\_\_ SIZE 10<sup>3</sup>/<sub>4</sub>"

CEMENT VOLUME \_\_\_\_\_ RETURNS \_\_\_\_\_

PROBABLE FOX HILLS DEPTH \_\_\_\_\_

MUD PITS NONE

DISPOSAL \_\_\_\_\_

PRODUCTION STRING \_\_\_\_\_ SIZE 5<sup>1</sup>/<sub>2</sub>" DEPTH 510'

STAGED \_\_\_\_\_ CBL CHECKED \_\_\_\_\_

SQUEEZE \_\_\_\_\_ FRAC JOB \_\_\_\_\_

BATTERY NONE SIGN NONE

SITE INSPECTION AFTER DRILLING 5<sup>1</sup>/<sub>2</sub>" CSG POORLY CAPPED - 5<sup>1</sup>/<sub>2</sub>" x 10<sup>3</sup>/<sub>4</sub>" ANNULUS OPEN AT SURFACE. CEMENT BASE AROUND 10<sup>3</sup>/<sub>4</sub>" SURFACE PIPE UNDERMINED - DROPPED ROCK INTO HOLE - HEARD ROCK FALLING, BUT NEVER HIT BOTTOM → POSSIBLE LEAK IN THE PAST - NONE NOW

NOT LEAKING

DIRECTIONS So. From LA JUNTA on Hwy 109 TO LAI ANIMAL CTY LINE - HEAD EAST ON ROAD AT COUNTY LINE FOR 4<sup>1</sup>/<sub>2</sub> mi ± TO GATE & ACCESS ROAD TO THE RIGHT.

ACTION Plug WellENGINEER ROBERT VACLAVIK

Please

☒ READ☐ HANDLE☐ APPROVE

and

☐ FORWARD☒ RETURN☐ KEEP OR DISCARD☐ REVIEW WITH MEDate 11/8/84

## ROUTING - REQUEST

To Jim McKeeFrom Robert V