

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283



Location ID required as entrance signs are replaced.



Wellhead sign missing API Number

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283




Tank battery sign missing required information



Debris

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283



Stained soils not completely removed



Insufficient cleanup of staining

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283



Soil staining scattered and incomplete




Debris still in place

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283



Debris still in place



Soil stains, spills and impacted soil need complete removal and proper disposal of waste

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283



Location view from Northeast corner



Location view from Northwest corner

GRMR Oil & Gas LLC
Myers 19-11HA
Loc ID: 441283



Location view from Southwest corner



Location view from Southeast corner