

GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



**Incomplete tank battery sign**



**Debris at entrance sign**

GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178




Operator contact information missing



Debris



**GRMR Oil & Gas LLC**  
**Hamil 19-16HA**  
**Loc ID: 442178**



**Debris**



**Spill? Staining around tank**



GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



Debris



Debris

GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



No operator contact information



Debris



GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



Condensate? Unmarked chemical container



Debris

GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



Debris



Debris



GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



**Stained soil**



**Debris**



GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178




Debris



Debris



**GRMR Oil & Gas LLC**  
**Hamil 19-16HA**  
**Loc ID: 442178**



**Debris**



**Unmarked chemical tank**



GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178




**No visible display of gas meter calibration**




**Hose not in use. Debris on the ground**



GRMR Oil & Gas LLC  
Hamil 19-16HA  
Loc ID: 442178



**Unmarked anchor**



**Stained soil**



**GRMR Oil & Gas LLC**  
**Hamil 19-16HA**  
**Loc ID: 442178**



**Location view from Northeast corner and location entrance**



**Location view from Southeast corner**



**GRMR Oil & Gas LLC**  
**Hamil 19-16HA**  
**Loc ID: 442178**



**Location view from Southwest corner**



**Location view from Northwest corner**