

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/GM 32-4

Location ID: 334754

Date: 8/24/2023



East Entrance to Location – Photo #06114



West End of Location – Photo #06116



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/GM 32-4

Location ID: 334754

Date: 8/24/2023



Wellheads – Photo #06115



Separators – Photo #06117



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/GM 32-4

Location ID: 334754

Date: 8/24/2023



**Tank Battery – Photo #06118**



**Location Lacks Stabilization – Photo #06119**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/GM 32-4

Location ID: 334754

Date: 8/24/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #06121