

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location ID: 324024

Date: 8/23/2023



Entrance to Location – Photo #06096



Wellhead – Photo #06098



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location ID: 324024

Date: 8/23/2023



Separator – Photo #06097



Rill Erosion on Access Road – Photo #06099



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/2NENE

Location ID: 324024

Date: 8/23/2023



**Rill Erosion on Access Road – Photo #06100**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #06101**