

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4MWME

Location ID: 334850

Date: 8/24/2023



SW Corner of Location – Photo #06123



NE Corner of Location – Photo #06125



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4MWME

Location ID: 334850

Date: 8/24/2023



Wellheads – Photo #06124



Separators – Photo #06126



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4MWME

Location ID: 334850

Date: 8/24/2023



**Tank Battery – Photo #06129**



**Unsecured Separator Hatches – Photo #06127**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4MWME

Location ID: 334850

Date: 8/24/2023



**Unsecured Separator Hatches – Photo #06128**