

# Interim and Stormwater Inspection

June 28, 2023

Operator: KP Kauffman Company Inc # 46290

Location ID: 319935

Inspection Document #:709400452

Adams, County

NESW, Section 3 2S64W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: UPRR 24 Pan Am C 2 Battery

Location ID: 319922



Photo 1. Photo of sign on site.



Photo 2. Photo of tank battery

**Inspection Photos**  
**Location Name: UPRR 24 Pan AM C 2 Battery**  
**Location ID: 319922**



**Photo 3. Photo taken of weeds and dumped trash onsite.**



**Photo 4. Photo of dumped trash (couch) on site.**



**Inspection Photos**  
**Location Name: UPRR 24 Pan AM C 2 Battery**  
**Location ID: 319922**



**Photo 5. Photo taken of weeds and dumped trash onsite.**



**Photo 6. See photo 5 comments.**



Inspection Photos  
Location Name: UPRR 24 Pan AM C 2 Battery  
Location ID: 319922



Photo 7. See photo 5 comments.



Photo 8. See photo 5 comments.