

# Interim & Stormwater Inspection

August 16, 2023

Operator: KP Kauffman Co, # 46290

Location ID: 328359

Inspection Document # 709400493

Weld, CO

SESE, 31 1N 67W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

# Inspection Photos

Location Name: Sack 44-31

Location ID: 328359



Aug 16, 2023 at 11:29:41 AM  
119 County Road 15  
Brighton CO 80603  
United States



Aug 16, 2023 at 11:29:57 AM  
119 County Road 15  
Brighton CO 80603  
United States

**Photo 1.** Photo of location sign on site.

**Photo 2.** Photo of well head.



# Inspection Photos

Location Name: Sack 44-31

Location ID: 328359



**Photo 3.** Photo of unused oily equipment/trash on site.



**Photo 4.** Photo of tree (russian olive) growing in well head,facing Northwest.



# Inspection Photos

Location Name: Sack 44-31

Location ID: 328359



**Photo 5.** Photo of weeds (kosha) on site facing east.



**Photo 6.** Photo of weeds (kosha) on site facing west.