

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 33-15 Pad

Location # 335064



Photo # 8275 From entrance to location



Photo # 8277 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 33-15 Pad

Location # 335064



Photo # 8278 Location



Photo # 8279 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 33-15 Pad

Location # 335064



Sep 6, 2023 at 10:16:44 AM
CO

Photo # 8280 Location



Sep 6, 2023 at 10:20:02 AM
CO

Photo # 8281 Unused equipment

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 33-15 Pad

Location # 335064



Photo # 8283 Open ended piping on production unit/wildlife hazard



Photo # 8285 Open ended pipe/wildlife hazard

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 33-15 Pad

Location # 335064



Photo # 8286 Open ended pipe/wildlife hazard



Photo # 8291 Open ended pipe/wildlife hazard