

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: Florida/3-65 27-26

Loc ID: 454192

Inspection: 709400438



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E




Exhibit F



Exhibit G

CA: Stormwater erosion above culvert from access road. Comply with Rule 1002.f.

CA Resolution: Operator has reported and provided photo evidence that the culverts have been repaired as of 9/7/2023 to comply with Rule 1002.f. Additional work has also been completed to address the identified stained soil. Soil has been properly removed and backfilled with clean road base to comply with Rule 905.e.