

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: King/3-65 28-29

Loc ID: 449176

Inspection: 709400440



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Trash observed onsite. Comply with rule 606.d.

CA Resolution: Identified trash observed on location has been addressed and removed to comply with Rule 606.d.

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Operator reports that tumbleweeds and debris have been cleared from the location to comply with Rule 606.c. Area will be monitored and maintained moving forward.