

# Inspection Photos

9/6/2023

Operator: CAERUS PICEANCE LLC - 10456

Location Number: 336019

Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location Number: 336019



**Photo 1:** Photos 1-2 taken from the central areas of the Location. Photos provide an overview from North, East, South and West.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location Number: 336019



September 6, 2023



September 6, 2023

**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 336019



**Photo 3:** Portajohn on the east end of the Location has not been secured.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location Number: 336019



**Photo 4:** Porta-johns on the west end, and at the Location entrance, have been secured.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 336019



September 6, 2023



September 6, 2023

**Photo 5:** Photos examples showing stained soils observed on the working pad surface, and stained soils stockpiled on the north end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 336019



**Photo 6:** Photos examples of trash debris observed on the working pad surface, and perimeter of Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location Number: 336019



**Photo 7:** Installation of Facilities “in process” at time of inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources