

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #1 Overview of tracking pad.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #2 View of tracking pad terminus.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #3 View of measured distance at tracking pad terminus.



Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #4 View of impacted material on ground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #5 View of improper material handling.



Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #7 View of impacted material on ground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #8 View of drill cuttings impacting the ground.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #11 View of unmarked tanks, with placard.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #12 View of no tank labeling.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #13 View of unsatisfactory BMP installation.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #14 View of no stormwater BMP installation.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #15 View of no BMP installation.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #16 View of no BMP installation.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #17 View of no wattle staking.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #18 View of no BMP installation.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Photo #19 View of oily rags not disposed in metal container.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #20 View of dried drilling additives.

Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



Nuevida Ardourel 33081718 4HU: Location ID/API #:067-10038



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #22 View of impacted ground.