

Inspection Photos

9/6/2023

Operator: CAERUS PICEANCE LLC - 10456

Location Number: 316202

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location Number: 316202



Photo 1: Photos provide overview of the working pad.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 316202




Photo 2: Photo taken from the northeastern corner of the Location. Photo left example showing anchors have not been properly identified with a marker of bright color not less than 4 feet in height. Photo right shows trash debris next to marker.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location Number: 316202



Photo 3: Photo example showing anchors have not been properly identified with a marker of bright color not less than 4 feet in height. Marker for the SW anchor missing.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location Number: 316202




Photo 4: Photos taken from the well. Photo left shows signage does not comport with ECMC requirements. Photo right shows unused barrel of “Paraffin” stored on Location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources