

Inspection Photos

9/6/2023

Operator: TEP ROCKY MOUNTAIN LLC -
96850

Location Number: 316591
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



Photo 1: Photos 1-2 taken from the east end of the working pad surface. Photos provide an overview of the Location from south, southwest, northwest to north. Photos also show interim reclamation of areas not needed for production have not been performed in accordance with 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



September 6, 2023



September 6, 2023

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



September 6, 2023



September 6, 2023

Photo 3: Photos 3-4 taken from the east end of the Location pad surface, within areas of the cutting trench. Photos provide an overview of the Location from south, southwest, northwest to north. Cutting trench has been closed/backfilled, however, photos also show interim reclamation of areas not needed for production have not been performed in accordance with 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



Photo 5: Topsoil stockpile on the north end of the Location; interim reclamation has not been performed, and segregated soils (including topsoil) have not been returned.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



Photo 6: Photos taken from the topsoil stockpile on the north end of the Location. Photo shows fence on Location has not been maintained.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



Photo 7: Photos examples showing Undesirable Plants Species on the Location have not been managed or removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location Number: 316591



Photo 8: Photos examples showing trash/debris remaining on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location Number: 316591



September 6, 2023



September 6, 2023

Photo 9: Photos examples showing unused equipment remaining improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



September 6, 2023



September 6, 2023

Photo 10: Photos examples showing unused equipment remaining improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 316591



Photo 11: Photo example showing unmarked anchors on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources