

Inspection Photos
Location Name: Stieber George B 1
Location ID: 335589



Photo 1 well head sign



Photo 2 overgrown vegetation

Inspection Photos
Location Name: Stieber George B 1
Location ID: 335589



Photo 3 overgrown vegetation and pumping unit pad



Photo 4 overgrown vegetation and pumping unit pad