

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad

Location ID: 430758



Photo # 8705 From entrance to location



Photo # 8706 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad

Location ID: 430758



Photo # 8707 Location



Photo # 8709 Unmarked deadman

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad

Location ID: 430758



Photo # 8710 Same unmarked deadman from a different angle