

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 9/6/2023



**East Entrance to Location/Weeds – Photo #06273**



**South End of Location/Weeds – Photo #06282**

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 9/6/2023



**Wellheads/Weeds – Photo #06274**



**Separators/Gas Meter Run/Weeds – Photo #06279**



## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 9/6/2023



**Separators/Gas Meter Run/Weeds – Photo #06280**



**Tank Battery/Weeds – Photo #06281**



## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 9/6/2023



**Tank Battery/Weeds – Photo #06278**



**Stained Soil Near Wellhead – Photo #06275**



## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 9/6/2023



**Stained Soil Near Wellhead – Photo #06276**



**Storage of Unused Equipment – Photo #06277**



## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 9/6/2023



**Access Road Lacks Stabilization – Photo #06285**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #06284**