

Interim Reclamation and Stormwater Inspection

August 23, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 470396

Inspection Document #: 697504814

Weld County, CO

SWNW Section 18 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: DAMORE/5-18HZ PAD

Location ID: 470396



Photo 1. Photo taken from the central location between the facility and well location, facing South. Photo illustrates unmanaged weeds.



Photo 2. Photo taken from the western well location, facing South. Photo illustrates the location and topsoil stockpiles with unmanaged weeds.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 697504814



Photo 3. Photo taken from the western topsoil stockpile, facing Northwest. See comments under Photo 2.



Photo 4. Photo taken from the northwestern interim reclamation area, facing Southeast. Photo illustrates most of the interim area consists of annual, weedy growth.

Reference crop is alfalfa.