

Inspection Photos

Location Name: CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 9/12/2023



North End of Location – Photo #06343



South End of Location – Photo #06344

Inspection Photos

Location Name: CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 9/12/2023



Wellhead – Photo #06345



Separator – Photo #06348

Inspection Photos

Location Name: CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 9/12/2023



Tank Battery – Photo #06347



Storage of Unused Equipment on Location – Photo #06349