

Inspection Photos

Location Name: CAERUS PICEANCE LLC, KM/C08 799

Location ID: 423633

Date: 9/12/2023



NW Corner of Location – Photo #06351



SW Corner of Location – Photo #06352

Inspection Photos

Location Name: CAERUS PICEANCE LLC, KM/C08 799

Location ID: 423633

Date: 9/12/2023



SE Corner of Location – Photo #06353



NW Corner of Location – Photo #06354

Inspection Photos

Location Name: CAERUS PICEANCE LLC, KM/C08 799

Location ID: 423633

Date: 9/12/2023



Wellheads/No Wellhead Sign Posted – Photo #06355



Separators – Photo #06358

Inspection Photos

Location Name: CAERUS PICEANCE LLC, KM/C08 799

Location ID: 423633

Date: 9/12/2023



Tank Battery – Photo #06357



ECD – Photo #06356