

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Kimball Mtn/B07 799

Location ID: 383216

Date: 9/12/2023



Wellhead/No Wellhead Sign Posted – Photo #06360



Separators – Photo #06361

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Kimball Mtn/B07 799

Location ID: 383216

Date: 9/12/2023



**Tank Battery – Photo #06362**

