

Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY-66S99W/24NENE

Location ID: 324260

Date: 9/13/2023



Wellhead – Photo #06367



Separator – Photo #06368

Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY-66S99W/24NENE

Location ID: 324260

Date: 9/13/2023



Sediment Run-On to Location – Photo #06371



Sediment Run-On to Location – Photo #06372

Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY-66S99W/24NENE

Location ID: 324260

Date: 9/13/2023



Location Lacks Stabilization – Photo #06373



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06374**