

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-66S99W/26SENW

Location ID: 311577

Date: 9/13/2023



Entrance to Location – Photo #06376



Wellhead – Photo #06377

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-66S99W/26SENW

Location ID: 311577

Date: 9/13/2023



Separator – Photo #06379



Tank Battery – Photo #06378

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-66S99W/26SENW

Location ID: 311577

Date: 9/13/2023



Rill Erosion Cutting Through Access Road – Photo #06380