

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8891 From entrance to location



Photo # 8892 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8893 Location



Photo # 8894 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Sep 12, 2023 at 12:26:40 PM
CO



Sep 12, 2023 at 12:26:59 PM
CO

Photo # 8895 Location

Photo # 8896 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Sep 12, 2023 at 12:26:18 PM
CO



Sep 12, 2023 at 12:30:08 PM
CO

Photo # 8897 Location

Photo # 8904 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8905 Location



Photo # 8906 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8907 Location

Photo # 8908 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8911 Location



Photo # 8912 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8913 Location



Photo # 8930 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8936 Location



Photo # 8915 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8919 Stained soils & gravel



Photo # 8921 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 23-17 Pad

Location ID: 452566



Photo # 8922 Stained soils & gravel



Photo # 8923 Stained soils & gravel