

Inspection Photos

Location Name: SCHMIER-65N64W/32NWNW

Location ID: 336634



Photo #1

Schmier 32-4A (123-14968) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 10 yds.



Photo #2

Schmier B 32-30D, B 32-31D, 32-4A pad

2: Temporarily Abandoned | TA

1: Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SCHMIER-65N64W/32NWNW

Location ID: 336634



Photo #3

Schmier B 32-30D, B 32-31D, B 32-32 Battery site

Inactive | Shut-down

Formerly served:

Schmier 32-4A, 32-5A, Thor B 32-19 ;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources