

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

707601837

**FIELD INSPECTION FORM**Loc ID 327645 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247172	WELL	PA	11/14/2018	GW	123-14969	SCHMIER 32-5A	PA

**General Comment:**

This is a PLUGGED &amp; ABANDONED WELL inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs

(336634, 302380).

(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged &amp; Abandoned | PA).

Centralized Battery formerly served 2 Location IDs

(305730, 327645).

(Well(s): 2: Plugged &amp; Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(447717).

(Battery: Inactive | Shut-down).

**Reference:**A.) Field Inspection Report doc. #707601829 and/or Location ID #336634  
for TA Well(s) info. (2).B.) Field Inspection Report doc. #707601831 and/or Location ID #302380  
for TA Well(s) info. (1).C.) Field Inspection Report doc. #707601833 and/or Location ID #336634  
for PA Well(s) info. (1).D.) Field Inspection Report doc. #707601835 and/or Location ID #305730  
for PA Well(s) info. (1).E.) Field Inspection Report doc. #707601837 and/or Location ID #327645  
for PA Well(s) info. (1).F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717  
for Battery / Facility, Equipment info.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 247172 Type: WELL API Number: 123-14969 Status: PA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 09/13/2023 at approximately 14:41 hrs. I, Bret Evins, conducted an onsite inspection at:            Operator Name: NOBLE ENERGY INC            Location Name: SCHMIER-65N64W/32SWNW            Location ID: 327645            Well Name(s):            Schmier 32-5A.            API:            123-14969.            Location County: Weld County, Colorado            Weather: Mostly Sunny, dry.</p> <p>While there, I observed:            Well(s): 1: Plugged &amp; Abandoned   PA.            Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (336634, 302380).            (Well(s): 3: Temporarily Abandoned   TA ;1: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery formerly served 2 Location IDs (305730, 327645).            (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (447717).            (Battery: Inactive   Shut-down).</p> <p>Reference:            A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2).            B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1).            C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1).            D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1).            E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1).            F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT:            Plugged &amp; Abandoned   PA.            Form 6S on file. Plugging, cut/cap date: 11/14/2018. Approved.            Plugged &amp; Abandoned   PA well GPS coordinates: 40.357380 / -104.580720</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/13/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601838	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250185</a>