

# Interim Reclamation and Stormwater Inspection

September 13, 2023

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 444710

Inspection Document #: 697504851

Weld County, CO

SESW Section 28 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: NGL C2 C & D  
Location ID: 444710



**Photo 1.** ECMC aerial imagery from 2021 illustrates the Class II Disposal Well and a portion of its flowline which travels to the NGL Major Facility (Location ID 443339).



Inspection Photos  
Location Name: NGL C2 C & D  
Location ID: 444710



**Photo 2.** Photo taken from the northeastern interim reclamation area, facing West. Photo illustrates the Operator has performed interim reclamation and desirable vegetation was observed; however, unmanaged tumbleweeds were observed.



**Photo 3.** Photo taken from the northeastern interim reclamation area, facing Southwest. See comments under Photo 2.



Inspection Photos  
Location Name: NGL C2 C & D  
Location ID: 444710



**Photo 4.** Photo taken from the eastern interim reclamation area, facing South. Photo illustrates an area of unmanaged tumbleweeds as the dominant vegetative growth.



**Photo 5.** Photo taken from the northeastern interim reclamation area along the flowline, facing Southwest. See comments under Photo 4.