

Interim Reclamation and Stormwater Inspection

September 13, 2023

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 443339

Inspection Document #: 697504855

Weld County, CO

SENE Section 28 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. Google Earth aerial imagery from 5/24/2023 illustrating the location. Operator has failed to perform interim reclamation around the well location (red polygon) and is storing equipment (orange arrows) on the well location.

Inspection Photos
Location Name: NGL MAJOR FACILITY C2
Location ID: 443339



Photo 2. Photo taken from the entrance of location, facing West. Photo illustrates the Operator sign.



Photo 3. Photo taken from the well location, facing West. Photo illustrates a shed over the wellhead.

Inspection Photos
Location Name: NGL MAJOR FACILITY C2
Location ID: 443339



Photo 4. Photo taken from the wellhead, facing North. Photo illustrates Operator has failed to perform interim reclamation.



Photo 5. Photo taken from the wellhead, facing West. See comments under Photo 4.

Inspection Photos
Location Name: NGL MAJOR FACILITY C2
Location ID: 443339



Photo 6. Photo taken from the wellhead, facing South. Photo illustrates Operator is storing equipment on the well location.



Photo 7. Photo taken from the wellhead, facing Southwest. See comments under Photo 6.