

Interim Reclamation and Stormwater Inspection

September 13, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 470407

Inspection Document #: 697504859

Weld County, CO

NWNW Section 18 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: PROWANT 4-18HZ PAD
Location ID: 470407



Photo 1. Photo taken from the northeastern interim reclamation area, facing West. Photo illustrates a MLVT has been constructed for subsequent well operations with heavy equipment. Operator has graded and disturbed the area for the purposes of constructing a MLVT.



Photo 2. Photo taken from the northeastern interim reclamation area, facing South. See comments under Photo 1.