

Interim Reclamation and Stormwater Inspection

September 13, 2023

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 323576

Inspection Document #: 697504861

Weld County, CO

NWSE Section 28 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: DAVID HOWARD #B-5
Location ID: 323576



Photo 1. Photo taken of the Operator sign at location.



Photo 2. Photo taken from the well location, facing North. Photo illustrates unmanaged tumbleweeds.



Inspection Photos
Location Name: DAVID HOWARD #B-5
Location ID: 323576



Photo 3. Photo taken from the well location, facing West. Photo illustrates unmanaged tumbleweeds and List B noxious weeds.