

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Photo 1 WH sign.



Photo 2 Undesirable vegetation growing tall around the WH.

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Photo 3 Undesirable vegetation around the WH & PJ.



Photo 4 Undesirable vegetation around the WH & PJ.

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Colorado Energy & Carbon Management Commission
40.1115, -104.92638, 4946.5ft
09/19/2023 12:46:31



Colorado Energy & Carbon Management Commission
40.11289, -104.9241, 4920.3ft
09/19/2023 12:51:14

Photo 5 Undesirable vegetation around the ancillary equip.

Photo 6 TB sign.

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Photo 7 Undesirable vegetation growing tall around TB area.



Photo 8 Undesirable vegetation growing tall around TB area.

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Photo 9 Undesirable vegetation growing tall around TB area.



Photo 10 Undesirable vegetation growing tall around the horizontal Heater Treater and Horizontal Heated Separator.

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Photo 11 Undesirable vegetation growing tall around the horizontal Heater Treater and Horizontal Heated Separator.



Photo 12 Undesirable vegetation growing tall around the horizontal Heater Treater and Horizontal Heated Separator.

Inspection Photos
Location Name: Tom L. Russell A 2
Location ID: 318279



Photo 13 Undesirable vegetation growing tall throughout location.