

Inspection Photos
Location Name: DeHaan V27-15
Location ID: 336206



Photo 1 WH sign operator information is faded and needs a new sticker.



Photo 2 WH.

Inspection Photos
Location Name: DeHaan V27-15
Location ID: 336206



Photo 3 Tall undesirable vegetation growing tall and needs to be addressed.