

Inspection Photos
Location Name: Vonasek 4
Location ID: 336206



Photo 1 WH sign.



Photo 2 WH.

Inspection Photos
Location Name: Vonasek 4
Location ID: 336206



Photo 3 Undesirable vegetation growing all around location and unused equipment.



Photo 4 Undesirable vegetation growing all around location and unused equipment.

Inspection Photos
Location Name: Vonasek 4
Location ID: 336206



Photo 5 Undesirable vegetation growing all around location and unused equipment.