

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2023

Submitted Date:

09/19/2023

Document Number:

701007347

**FIELD INSPECTION FORM**Loc ID 303715 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253515	WELL	PR	07/01/2015	GW	125-07392	ROSE 3-19	PR

**General Comment:**

Routine Inspection

**Location****Lease Road:**

Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign mounted to fence by wellhead		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Metal panels around meter shed and VGS		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 253515	Type: WELL	API Number: 125-07392	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing. Casing production			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT