

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost site. Location is within Rule 411a Surface Water Intermediate Buffer & Rule 411a Surface Water External Buffer.
Section/Township/Range: 33 6S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9613 Erosion on slope & transport of sediment onto location



Photo # 9615 Erosion on slope & transport of sediment onto location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9617 Erosion & transport of sediment on location



Photo # 9618 Erosion & transport of sediment on location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9673 Check dam needs maintenance



Photo # 9619 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9620 Erosion & transport of sediment on access road

Photo # 9621 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9622 Erosion & transport of sediment on access road



Photo # 9623 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9626 Erosion & transport of sediment on access road

Photo # 9628 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9682 Erosion & transport of sediment on access road



Photo # 9683 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9629 Erosion & transport of sediment on access road

Photo # 9630 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9631 Erosion & transport of sediment on access road



Photo # 9633 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9634 Erosion & transport of sediment on access road

Photo # 9635 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9636 Erosion & transport of sediment on access road



Photo # 9638 Erosion & transport of sediment on access road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9641 Erosion & transport of sediment on access road & then onto location & into vegetated areas



Photo # 9642 Erosion & transport of sediment on access road & then onto location & into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9643 Erosion & transport of sediment on access road & then onto location & into vegetated areas



Photo # 9644 Erosion & transport of sediment on access road & then onto location & into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9645 Erosion & transport of sediment on access road & then onto location & into vegetated areas



Photo # 9648 Erosion & transport of sediment on access road & then onto location & into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9668 Sediment transported from access road onto location & into vegetated areas

Photo # 9669 Sediment transported from access road onto location & into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9652 Erosion & transport of sediment on access road & then onto location & into vegetated areas



Photo # 9655 Erosion & transport of sediment on access road & then onto location & into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9656 Erosion & transport of sediment into vegetated areas



Photo # 9657 Erosion & transport of sediment into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9658 Erosion & transport of sediment into vegetated areas



Photo # 9659 Erosion & transport of sediment into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Sep 18, 2023 at 11:44:38 AM
CO



Sep 18, 2023 at 11:45:05 AM
CO

Photo # 9660 Erosion & transport of sediment into vegetated areas

Photo # 9662 Erosion & transport of sediment into vegetated areas

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 43-33 Pad
Location ID: 335303



Photo # 9664 Erosion & transport of sediment into vegetated areas



Photo # 9665 Erosion & transport of sediment on access road & then onto location & into vegetated areas