

Inspection Photos
Location Name: DF Ranch 2-33 Tank Battery
Location ID: 461586



Photo 1 – Barbed Wire and Signs on NE Corner of Tank Battery



Photo 2 – ECD and Heater Treaters

Inspection Photos
Location Name: DF Ranch 2-33 Tank Battery
Location ID: 461586



Photo 3 – Tank Battery



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: DF Ranch 2-33 Tank Battery
Location ID: 461586




Photo 5 – Content and Capacity Labels have faded no longer visible




Photo 6 – Stained Soil

Inspection Photos
Location Name: DF Ranch 2-33 Tank Battery
Location ID: 461586



Photo 7 – Stained Soil



Photo 8 – Stained Soil