

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 1 Location.

Photo 2 WH sign.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 3 WH.



Photo 4 Pump Jack.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 5 Marked Dead man anchors covered with tall undesirable vegetation.

Photo 6 Marked Dead man anchors covered with tall undesirable vegetation.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 5 Marked Dead man anchors covered with tall undesirable vegetation.



Photo 6 Marked Dead man anchors covered with tall undesirable vegetation.